

Ensurepass.com Easy Test! Easy Pass!



Vendor: Cisco

Exam Code: 640-792

Exam Name: Supporting Cisco TelePresence System Devices
v1.0 (TPTECH)

Version: DEMO

QUESTION 1

Which port is indicated on the right Secondary Codec for the CTS-3210?

- A. Right Display
- B. Right Camera
- C. Center Display
- D. Left Display

Answer: B

QUESTION 2

Which port do you connect to on the Primary Codec in order to establish an Ethernet connection between your laptop and the Cisco TelePresence 3000 equipment?

- A. Video port
- B. Network port
- C. IP Phone port
- D. Secondary Camera port

Answer: B

QUESTION 3

Which size and type of tool is required to loosen the screws that allow rotational adjustment of the CTS-3010 cameras?

- A. #1 Phillips screwdriver
- B. 5.0 mm Allen wrench
- C. #3 Phillips screwdriver
- D. 3.0 mm Allen wrench

Answer: D

QUESTION 4

Which four functions does Cisco TelePresence rely on Cisco Unified Communications Manager for? (Choose four)

- A. Configurations
- B. Software upgrades
- C. Management
- D. Call processing
- E. Scheduling meetings
- F. Microphone calibration

Answer: ACDE

QUESTION 5

Which three of the following components are included on the Cisco TelePresence 3210? (Choose three.)

- A. One boardroom-style table with a second row
- B. One boardroom-style table
- C. One 40" external display
- D. Nine table microphones
- E. Four LED light fixtures

Answer: ACD

QUESTION 6
DRAG DROP

Click and drag the OSI reference layer on the left to the corresponding Internet protocol suite on the right.

Layer 2 - Data Link	IP
Layer 3 - Network	Email
Layer 4 - Transport	TCP
Layer 7 - Application	ARP

Answer:

Click and drag the OSI reference layer on the left to the corresponding Internet protocol suite on the right.

Layer 2 - Data Link	Layer 3 - Network
Layer 3 - Network	Layer 7 - Application
Layer 4 - Transport	Layer 4 - Transport
Layer 7 - Application	Layer 2 - Data Link

QUESTION 7

Which three of the following are benefits of Cisco TelePresence Manager? (Choose three)

- A. Bulk software upgrades of endpoints
- B. Calendaring integration and management
- C. One-Button-to-Push meeting access
- D. Allow for content sharing
- E. Concierge services

Answer: BCD

QUESTION 8

Which two hardware components are optional for the Cisco TelePresence 1000? (Choose two)

- A. One Cisco Unified IP Phone 7975G
- B. One external display
- C. One high-definition camera
- D. One Auxiliary Control Unit

Answer: AD

QUESTION 9

Which port is indicated on the Auxiliary Control Unit for the CTS-1100 and 1300?



- A. Auxiliary Collaboration Display
- B. Serial Control for Projector
- C. Lights
- D. Serial Control for Dimmer Box

Answer: B

QUESTION 10

DRAG DROP

Click and drag the Cisco TelePresence model on the left to the number of participants the unit is designed for on the right:

CTS-500	2 participants in a multipurpose room
CTS-1100	Up to 18 participants in dedicated TelePresence room
CTS-1300	1-2 participants in a home/ executive Office
CTS-3010	6 participants in a multipurpose room
CTS-3210	6 participants in a dedicated TelePresence room

Answer:

Click and drag the Cisco TelePresence model on the left to the number of participants the unit is designed for on the right:

CTS-500	CTS-1100
CTS-1100	CTS-3210
CTS-1300	CTS-500
CTS-3010	CTS-1300
CTS-3210	CTS-3010

Ensurepass.com Members Features:

1. Verified Answers researched by industry experts.
2. Q&As are downloadable in PDF and VCE format.
3. 98% success Guarantee and **Money Back** Guarantee.
4. Free updates for **180** Days.

View list of All Exam provided:

<http://www.ensurepass.com/certifications?index=A>

To purchase Lifetime Full Access Membership click here:

<http://www.ensurepass.com/user/register>

Valid Discount Code for 2014: SFOH-FZA0-7Q2S

To purchase the HOT Exams:

<u>Cisco</u>		<u>CompTIA</u>		<u>Oracle</u>	<u>VMWare</u>	<u>IBM</u>
<u>100-101</u>	<u>640-554</u>	<u>220-801</u>	<u>LX0-101</u>	<u>1Z0-051</u>	<u>VCAD510</u>	<u>C2170-011</u>
<u>200-120</u>	<u>640-802</u>	<u>220-802</u>	<u>N10-005</u>	<u>1Z0-052</u>	<u>VCP510</u>	<u>C2180-319</u>
<u>300-206</u>	<u>640-816</u>	<u>BR0-002</u>	<u>SG0-001</u>	<u>1Z0-053</u>	<u>VCP550</u>	<u>C4030-670</u>
<u>300-207</u>	<u>640-822</u>	<u>CAS-001</u>	<u>SG1-001</u>	<u>1Z0-060</u>	<u>VCAC510</u>	<u>C4040-221</u>
<u>300-208</u>	<u>640-864</u>	<u>CLO-001</u>	<u>SK0-002</u>	<u>1Z0-474</u>	<u>VCP5-DCV</u>	<u>RedHat</u>
<u>350-018</u>	<u>642-467</u>	<u>ISS-001</u>	<u>SK0-003</u>	<u>1Z0-482</u>	<u>VCP510PSE</u>	<u>EX200</u>
<u>352-001</u>	<u>642-813</u>	<u>JK0-010</u>	<u>SY0-101</u>	<u>1Z0-485</u>		<u>EX300</u>
<u>400-101</u>	<u>642-902</u>	<u>JK0-801</u>	<u>SY0-301</u>	<u>1Z0-580</u>		
<u>640-461</u>	<u>700-302</u>			<u>1Z0-820</u>		

